



Note: The L.H. seat switch at the bulb check relay is shown "as wired" in this car. It is not functional.

- |                |                |
|----------------|----------------|
| B=black        | P=purple       |
| G=green        | R=red          |
| K=pink         | S=slate (gray) |
| LG=light green | U=blue         |
| N=brown        | W=white        |
| O=orange       | Y=yellow       |

*Spitprint 76*  
 1976 Triumph Spitfire, Federal Version  
 "Beta" 11/21/98 tomomalley@meganel.net  
 FM50855U AUG 1976